

Attachment A: Digital Images

Page 1 of 5

September 2nd, 2008

BOE Building 23rd Floor Wide Post Mitigation Assessment
Sacramento, CA



- 1) Image of ambient air sampling location on West side of 23rd Floor Balcony located at 450 N Street, Sacramento, California (Subject Building) at time of assessment.



- 2) Image of air sampling performed within southwestern corner of 23rd floor (office 2309) at time of clearance inspection and sampling assessment.



3) Image of air sampling equipment operated within area 2305 at time of assessment.



4) Image of physical layout within room 2305 located at center segment of southern perimeter wall within 23rd Floor.



- 5) Image of air sampling activity performed within room 2339 at southeastern corner of 23rd floor at time of assessment.



- 6) Image of structures and sampling equipment within office 2335 located along eastern side of 23rd floor at time of assessment.



- 7) Image of structures and sampling equipment within office 2332 located along northeastern corner of 23rd floor at time of assessment.



- 8) Image of air sampling performed within northern hallway of 23rd floor of subject building at time of assessment.



- 9) Image of air sampling performed within south hallway of 23rd floor of subject building at time of assessment.



- 10) Image of ambient air sampling performed on northern balxony of 23rd floor at time of assessment.